PHOSPHORIC ACID

PHOSPHORIC ACID is a clear colorless liquid or transparent crystalline solid. The pure solid melts at 42.35° C and has a density of $1.834 \, \text{g}$ / cm3. Liquid is usually an 85% aqueous solution. Shipped as both a solid and liquid. Corrosive to metals and tissue. Used in making fertilizers and detergents and in food processing.